

BOARD MEETING DATE: 10/21/2025

ITEM NO: X-e

RECOMMEND THAT the Board approve the Annual Comprehensive Safety
Inspection Report.

ANNUAL COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULE - SREF 2012 & F.A.C. 69A-58
FISCAL YEAR 2025-2026

College Facility: North Florida College Fire District: Madison
SCHOOL / FACILITY: Perry Center
ADDRESS: 319 North Byron Butler Parkway, Perry FL 32347

OF SERIOUS FIRE SAFETY VIOLATIONS 0

OF NON-SERIOUS FIRE SAFETY VIOLATIONS 0

FIRE DISTRICT FIRE SAFETY INSPECTOR NAME PRINTED (IF JOINT INSPECTION)

Jeb W. Bynum (Municipal Fire Safety Inspector)
CONTRACTED COMM. COLLEGE BOARD FIRE SAFETY INSPECTOR NAME PRINTED

September 19, 2025
INSPECTION DATE

FIRE DISTRICT FIRE SAFETY INSPECTOR SIGNATURE (IF JOINT INSPECTION)

Fire Prevention Specialists, Inc., 609 Gina Lane, Melbourne, FL 32940 321-302-3993
INSPECTOR ADDRESS & PHONE NUMBER

133209
FIRE INSPECTOR CERTIFICATION NUMBER

SIGNATURE DATE FIRE INSPECTOR CERTIFICATION NUMBER

9/21/2025
COLLEGE BOARD FIRE SAFETY INSPECTOR SIGNATURE / DATE

LOCATION:

Deficiency locations will be identified by a building number followed by the room number (e.g. 2-505 or 1-133A). These numbers are usually affixed above the door leading into that particular room. Or if the deficiency is in an area without an identifiable room number, the area in question will be specifically identified. For example: Pressbox, Field House, Pavilion, etc.

North Florida College has met the requirements of F.S.S. 1013.12(2)(d): X YES ___ NO

Approval of Reports by Board (Including Letter) ___ YES ___ NO

THE UNDERSIGNED ATTESTS TO THE REVIEW OF THIS REPORT IN ITS ENTIRETY AND ACKNOWLEDGES AWARENESS OF THE DISCOVERED DEFICIENCIES.

Glenn Strickland

FACILITY ADMINISTRATOR NAME PRINTED

Physical Plant Director

FACILITY ADMINISTRATOR TITLE

Glenn Strickland

FACILITY ADMINISTRATOR SIGNATURE

9-22-2025

SIGNATURE DATE

[illegible]

ANNUAL COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULE - SREF 2012 & F.A.C. 69A-58
FISCAL YEAR 2025-2026

College Facility: North Florida College Fire District: Madison
SCHOOL / FACILITY: Main Campus
ADDRESS: 325 Turner Davis Drive, Madison, FL 32340

OF SERIOUS FIRE SAFETY VIOLATIONS 0
OF NON-SERIOUS FIRE SAFETY VIOLATIONS 0

FIRE DISTRICT FIRE SAFETY INSPECTOR NAME PRINTED (IF JOINT INSPECTION) _____

Jeb W. Bynum (Municipal Fire Safety Inspector)
CONTRACTED COMM. COLLEGE BOARD FIRE SAFETY INSPECTOR NAME PRINTED _____

September 19, 2025
INSPECTION DATE

FIRE DISTRICT FIRE SAFETY INSPECTOR SIGNATURE (IF JOINT INSPECTION) _____

Fire Prevention Specialists, Inc., 609 Gina Lane, Melbourne, FL 32940 321-302-3993
INSPECTOR ADDRESS & PHONE NUMBER

9/21/2025

133209

SIGNATURE DATE _____ FIRE INSPECTOR CERTIFICATION NUMBER _____

FIRE INSPECTOR CERTIFICATION NUMBER

LOCATION:

Deficiency locations will be identified by a building number followed by the room number (e.g. 2-505 or 1-133A). These numbers are usually affixed above the door leading into that particular room. Or if the deficiency is in an area without an identifiable room number, the area in question will be specifically identified. For example: Pressbox, Field House, Pavilion, etc.

North Florida College has met the requirements of F.S.S. 1013.12(2)(d): X YES NO

Approval of Reports by Board (Including Letter) YES NO

THE UNDERSIGNED ATTESTS TO THE REVIEW OF THIS REPORT IN ITS ENTIRETY AND ACKNOWLEDGES AWARENESS OF THE DISCOVERED DEFICIENCIES.

Glenn Strickland
FACILITY ADMINISTRATOR NAME PRINTED
Physical Plant Director
FACILITY ADMINISTRATOR TITLE

Glenn Strickland
FACILITY ADMINISTRATOR SIGNATURE
9-22-25
SIGNATURE DATE

CODE NUMBER	SREF 2025/2026 Fire Safety Deficiencies - Main Campus		Prior Times Cited	Deficiency Corrected By	Date Deficiency Corrected	Line No.
	Location, Deficiency Description					
	01 Bldg.: No deficiencies noted					1
	02 Bldg.: No deficiencies noted					2
	03 Bldg.: No deficiencies noted					3
	04 Bldg.: No deficiencies noted					4
	05 Bldg.: No deficiencies noted					5
	06 Bldg.: No deficiencies noted					6
	07 Bldg.: No deficiencies noted					7
	08 Bldg.: No deficiencies noted					8
	09 Bldg.: No deficiencies noted					9
	10 Bldg.: No deficiencies noted					10
	11 Bldg.: No deficiencies noted					11
	12-116: Rated door not latching					12
	13 Bldg.: No deficiencies noted					13
	14 Building: No deficiencies noted					14
	15 Greenhouses: No deficiencies noted					15
	16 Building: No deficiencies noted					16
	17 Building: No deficiencies noted					17
	18 Building: No deficiencies noted					18
	19 Building: No deficiencies noted					19
	20 Building: No deficiencies noted					20
	21, 22, 23, 25, 26, 27 Bldgs.: Softball & Baseball facilities not used					21
	32 Building: No deficiencies noted					22
	33 Building: No deficiencies noted					23
	34 Building: No deficiencies noted					24
	35 Building: No deficiencies noted					25
	36 Building: No deficiencies noted					26
						27
						28
						29
						30